

Processing Record for this file:
(Make notes here unique for this file)


Loading 10/1/2014 - 11/1/2014

Data loaded from DMF (detarred, unzipped and names restored)


Several short (4-s) data spikes of unknown origin.

Data appear normal and reliable. Internal calibrations consistent and very stable.


TEI Model 49i UV Photometric Ozone Analyzer



TEI Model 49i UV Photometric Ozone Analyzer
Housekeeping




TEI Model 49i UV Photometric Ozone Analyzer Zero/Span Checks




Project/Platform/Site: maomaoscs1
ARM Climate Research Facility
Contact: S.R. Springston (631) 344-4477, srs@bnl.gov

TEI Model 49i UV Photometric Ozone Analyzer
Baseline Corrected




TEI Model 49i UV Photometric Ozone Analyzer
Baseline Corrected




Project/Platform/Site: maomaoscs1
ARM Climate Research Facility
Contact: S.R. Springston (631) 344-4477, srs@bnl.gov

TEI Model 49i UV Photometric Ozone Analyzer
Baseline Corrected




TEI Model 49i UV Photometric Ozone Analyzer
Baseline Corrected




Project/Platform/Site: maomaoscs1
ARM Climate Research Facility
Contact: S.R. Springston (631) 344-4477, srs@bnl.gov

TEI Model 49i UV Photometric Ozone Analyzer
Baseline Corrected



TEI Model 49i UV Photometric Ozone Analyzer
Baseline Corrected



Project/Platform/Site: maomaoscs1
ARM Climate Research Facility
Contact: S.R. Springston (631) 344-4477, srs@bnl.gov